
A142 - COPPER INGOT





A142.1

Identification

A142 Sample: Card reference: S73

Antique shipwreck Origin:

Location: n/a

Description


Large crystals and numerous inclusions.

Figure captions A142.1


General view of the cross section: numerous sulphide inclusions, many of them decorating the grain boundaries.

A142.2


Surface detail: corrosion penetrating intergranularly.



A142.2



A142.1 General view of the cross section: numerous sulphide inclusions, many of them decorating the grain boundaries.



A142.2 Surface detail: corrosion penetrating intergranularly.